

# WH0100 Wireless In/Out Thermometer with Humidity



## Features:

- 1) Indoor temperature (°C or °F)
- 2) Remote temperature (°C or °F)
- 3) Remote humidity
- 4) One WH2 transmitter included
- 5) Free standing or wall mount
- 6) Minimum and maximum memory
- 7) Low power consumption (approx. 2 years battery life)

## Specifications:

- 1) Humidity range: 20% - 95% (+/-5% under 0 to 45°C)
- 2) Remote temperature range: -40 ~ +65°C
- 3) Indoor temperature range: 0 ~ +60°C
- 4) Temperature accuracy: +/-1.0°C
- 5) Transmission frequency: 433MHz
- 6) Transmission range: up to 100m line of sight

## Power requirements:

- Base station: 2 x "AA" alkaline batteries (not included)  
Sensor : 2 x "AAA" alkaline batteries (not included)

## Dimensions:

- Base station: 113 x 67 x 27.5mm  
Sensor : 91 x 70 x 32.5mm

## Distributor:

**AWR Smith Process Instrumentation cc**

PO Box 449 Pinegowrie 2123

Tel: 011 782 7279 / 888 7144 Fax: 086 648 7664

e-mail: [sales@instruments.co.za](mailto:sales@instruments.co.za) website: [www.instruments.co.za](http://www.instruments.co.za)